

# Use of Advanced Monitoring Technology to Detect Incipient Failure of Line Equipment

71st Annual Conference for Protective Relay Engineers  
Texas A&M University  
College Station, Texas USA  
26-29 March 2018

Victor Thompson  
Director, Engineering and Operations  
vthompson@cvec.coop  
325-655-6957  
Concho Valley Electric Cooperative  
San Angelo, Texas

Carl L. Benner, P.E.  
Research Associate Professor  
carl.benner@tamu.edu  
979-676-0499  
Texas A&M Engineering  
College Station, Texas


# Background

## DFA Technology

- Conventional distribution operations have limited awareness of circuit events and conditions.
- DFA technology, developed by Texas A&M Engineering, continuously monitors conventional CTs and PTs, with high fidelity, and applies sophisticated waveform classification software to detect circuit events, including incipient failures. It reports them to personnel for action.
- Improved visibility of circuit events enables improved circuit management and operations.

# Background

## DFA Monitoring Topology



Each substation-installed DFA Device runs waveform analysis and classification software and then sends results to a central DFA Master Station. Personnel access DFA results via browser connection to the DFA Master Station.

# Background

## Texas Power Line-Caused Wildfire Mitigation Project

- Because many wildfires result from power line events, the Texas legislature established the Texas Power Line-Caused Wildfire Mitigation project, based on Texas A&M Engineering's DFA technology.
- Participants instrumented 60+ circuits with DFA circuit monitors.
  - Austin Energy
  - Bluebonnet Electric Coop
  - BTU (Bryan Texas Utilities)
  - Concho Valley Electric Coop
  - Mid-South Synergy Electric Coop
  - Pedernales Electric Coop
  - Sam Houston Electric Coop
  - United Cooperative Services
- Most DFA circuit monitors have been installed 2-3 years.
- Multiple participants are expanding deployments in 2018.

# Background

## Texas Power Line-Caused Wildfire Mitigation Project

### Partial List of Events Detected and Corrected by Project Participants

- Detection and repair of substantial number of routine outages, without customer calls.
- Detection and location of tree branch hanging on line and causing intermittent faults.
- Detection and location of intact tree intermittently pushing conductors together.
- Detection and location of broken insulator that resulted in conductor lying on and heavily charring a wooden crossarm.
- Detection and location of catastrophically failed lightning arrester.
- Detection and location of arc-tracked capacitor fuse barrel.
- Detection and location of multiple problems with capacitor banks.




Most events have potential for fire ignition and also affect reliability and service quality.

# Case Study

## Concho Valley Electric Cooperative 31-Day Incipient Clamp Failure



# The Series Arcing Phenomenon



- Series arcing occurs when a current-carrying device develops a “hot spot” and represents incipient failure of the device.
  - Contacts of clamps, switches, and cutouts (many documented by DFA program).
  - Maybe splices, but these have not been documented by DFA program.
- Whereas conventional faults cause current to flow in unintended paths, series arcing interferes with current flow in an intended path.
- Field experience with DFA demonstrates that series arcing often occurs for hours to weeks before a device fully fails and causes an outage.
- Before final failure, series arcing may cause intermittent, hard-to-diagnose issues, including blown fuses, momentary trip/closes, flickering lights, ....

# Case Study

## 31-Day Series Arcing (Incipient Clamp Failure)

### Subject circuit

- 25 kV
- Conventional four-wire overhead
- 268 miles of exposure, 44.9 miles furthest extent
- 427 active meters
- Almost entirely oilfield load
- RF-based AMI across entire system

# Failing Switch/Clamp Report from DFA

			Single-phase fault	C	Short-lived fault	N/A	2017-10-25 08:50:11
Probable failure of switch or clamp			B	Estimated load beyond switch/clamp: 194 kVA 80% likelihood switch; 20% likelihood clamp			496 transients (31 days)
			Multi-phase trip	BC	F-(1.5c,417A,BCN)-T-(4,6,4)%	1 op	2017-10-24 10:59:58
			Probable failure of switch or clamp	B	Estimated load beyond switch/clamp: 194 kVA 80% likelihood switch; 20% likelihood clamp	496 transients (31 days)	2017-10-24 10:07:15
			Single-phase fault	C	Short-lived fault (May affect fault current accuracy) (Experimental) Possible Causes: 80% Animal, 15% Arrester F-(15ms,491A,CN)	N/A	2017-10-23 00:52:52


# Failing Switch/Clamp Report from DFA

Expand	Substation	Circuit	Event Type	Phases	Comments	Count	Last Occurred
			Probable failure of switch or clamp	B	Estimated load beyond switch/clamp: 194 kVA 80% likelihood switch; 20% likelihood clamp	496 transients (31 days)	2017-10-24 10:07:15

Export    Show  entries    Search:


Event Type	Phases	Phase A Amps	Phase B Amps	Phase C Amps	Transients	Last Occurred
Probable failure of switch or clamp(C)	B	14	108	10	1	2017-10-24 10:07:15
Probable failure of switch or clamp(S)	B	10	64	8	6	2017-10-24 09:41:26
Probable failure of switch or clamp(I)	B	9	70	8	3	2017-10-24 09:11:26
Probable failure of switch or clamp(I)	B	5	57	6	2	2017-10-24 06:52:43
Probable failure of switch or clamp(I)	B	8	37	7	1	2017-10-24 06:51:30
Probable failure of switch or clamp(I)	B	8	102	8	1	2017-10-24 06:50:21
Probable failure of switch or clamp(I)	B	7	91	10	2	2017-10-24 06:45:25
Probable failure of switch or clamp(I)	B	8	45	6	1	2017-10-24 06:44:54
Probable failure of switch or clamp(I)	B	7	50	6	1	2017-10-24 06:36:18
Probable failure of switch or clamp(I)	B	10	101	8	1	2017-10-24 06:35:20

# Intermittency of Series Arcing




- DFA recorded 250 events in 31 days.
  - 174 were during the final five days.
  - Days 2-12 registered no events.
  - Peak activity was 63 events on day 28.
  - Activity generally increased over time, but not steadily or predictably.
- Most of the total period was quiescent.
  - $(250 \times 10) / (31 \times 24 \times 60 \times 60) = 0.1\%$ .
  - No activity was recorded 99.9% of time.
- Intermittency makes location with RF, thermal imaging, ... difficult.

# Subject Circuit – Normal Load



- Graphs come from DFA recordings, which come from conventional circuit CTs and bus PTs at substation.
- Most DFA recordings are 10+ seconds at 256 samples/cycle.
- RMS (one value per cycle) is shown to give “the big picture.”
- Subject circuit is mostly oilfield load.
- Variability shown in this graph is normal for this circuit.

# Line Current and Voltage During Series Arcing Event



- Voltage variations are  $< 1\%$ .
- Current variations:
  - Peaks of several tens of amperes
  - Highly unstable and intermittent.
  - Magnitudes similar to large loads and inrush events.
- Peaks have sufficient magnitude to trip sensitive overcurrent protection, but limited duration.
- Event signature is subtle.

# Challenges of Locating Series Arcing

- For series arcing, current amplitude is largely a function of connected kVA capacity downstream of the failing device, rather than line impedance. Therefore impedance-based fault location methods are ineffective.
- RF and thermal diagnostics might be effective if applied during an active flare-up, but flare-ups occur only a tiny percentage of the time.
- Clamp failures may operate protection in the path upstream or downstream of the failing device. (The “downstream” part is counterintuitive, but it is readily explained by theory and has been documented multiple times by DFA field installations.)

# Concho's Search Process and Learnings

- This was Concho's first attempt to locate series arcing.
- Circuit model identified 18 circuit locations that fit DFA parameters.
- Murphy's Law was in full force – clamp was at last location.
- (Murphy cont'd) Conductor burned in two, ending series arcing, right before Concho arrived to check that location. AM radio got a "hit."
- Clamp was on phase B on the source side of a hydraulic E recloser.
  - Bank of three single-phase reclosers, type E, 50A pickup, 2A2B.
  - Since last check, operations counters had incremented by 3 (A), 27 (B), and 2 (C). It is believed that many of the phase-B "counts" resulted from the clamp.
- Concho expected that the AMI system would have data relevant to location of a clamp, but in this case it did not.

# The Culprit



# Summary and Conclusions

- Concho spent 40 hours searching for this clamp, but learned lessons that should make the process more efficient next time, and considers this a successful first use.
- Sophisticated, automated analysis of high-fidelity data from conventional CTs and PTs can provide improved awareness of circuit events, which can enable better circuit operation.
- When used synergistically with circuit models, AMI, etc., some events are readily located (e.g., most recurrent faults, fault-induced conductor slap); others are more challenging.
- The first use of a new technology or process often is difficult, but lessons can be learned and processes improved.

# Use of Advanced Monitoring Technology to Detect Incipient Failure of Line Equipment

71st Annual Conference for Protective Relay Engineers  
Texas A&M University  
College Station, Texas USA  
26-29 March 2018

Victor Thompson  
Director, Engineering and Operations  
vthompson@cvec.coop  
325-655-6957  
Concho Valley Electric Cooperative  
San Angelo, Texas

Carl L. Benner, P.E.  
Research Associate Professor  
carl.benner@tamu.edu  
979-676-0499  
Texas A&M Engineering  
College Station, Texas