Analysis of Multiple Misoperations following an External Fault


Ed Chen – Con Edison

Richard Hunt– Quanta Technology



Introduction

- Consolidated Edison Company of New York, Inc. (Con Edison) is one of the largest investor-owned utilities in the world.
 - Established in 1823
 - Provides electric, gas and steam services to 9 million people
 - Owns 94,000 miles of underground cable and 34,000 miles of overhead conductors.
- Distribution system at three different voltage levels: 33kV, 27kV and 13kV.





Event Scheme

• 33kV Feeder Protection

 Protected by Phase to Phase and Phase to Ground relays.


Instantaneous and Time over Current elements.

• 138kV Ring Bus and Transmission Feeder Protection

Dedicated Local Breakers

 Connected to the high side delta transformer windings.

Protected by Line
 Differential relays.





Remote Area Dist Sub Fault event Ring Bus Feeder B Feeder D Feeder G **Feeder B Tripped** Local Station 138 kV **Normally Open** XFMR Feeder E Feeder F 5 4 Feeder C Feeder A **Feeder A Tripped** 33 kV Ring Bus **Protection Cleared Correctly**


Feeder Fault

Multiple Distribution Feeders



Event Scheme

- Line Differential Protection
- External Summation of CTs:
 - Two (2) 138kV bus section breakers CTs
 - Transmission Feeder breakerCT
 - Transformer high side CT connected by Auxiliary CTs.
- Transfer trip to Remote End.
- Limited Relay CT inputs.






Steps to analyze this event

- Verify protection settings, coordination, short circuit model
- Field verify relay secondary circuits, connections
 - Emphasis on actual burden, CT performance
- Model relay circuits and analyze performance




What do we know about the fault?






Feeder A arrangement



- Feeder A and Feeder B have the same functional arrangement
 - Relay parallels 4 CTs as an input to the relay
 - Essentially measures an error current at all times
- How to determine if this was CT saturation
 - Not a typical waveform for a saturated CT for a fault




Feeder A CT secondary circuits




- One of these CTs is not like the others:
 - Transformer A has a 1200:5 bushing CT tapped to 600:5.
 - Uses an auxiliary CT for turns ratio correction
- Relatively high connected burdens on these CTs



2000:5 CT Analysis






Used PSRC CT Saturation Calculator to model the Breaker 8 (I₂ current) CT that sees almost all the fault current

No saturation - none of the 2000:5 CTs will saturate for the available fault current, even fully offset




Auxiliary CT analysis




No saturation for this fault event – will faithfully reproduce the output of the bushing CT.




Transformer A bushing CT analysis






C200 tapped down to 50% winding (effectively a C100), high connected burden

What does the relay see






Relay error current






Differential relay operation




Used a 1-cycle DFT to calculate a phasor quantity for the CT error current



Why didn't the transformer differential operate?





- Modeled characteristic in CT Saturation Calculator
 - Saturated high-side CT
 - Unsaturated low-side CT
 - Enough differential current to operate
- Answer: 2nd harmonic restraint
 - Calculated 2nd harmonic of saturated CT in CT Saturation Calculator



Event Testing and Results

- Secondary Circuit Burden Test
 - Full circuit burden test.
 - The A Phase had a high burden of 4 ohms.
- Current Transformer Excitation Test
 - All nameplate values were confirmed.
 - The 600/5 Transformer CTs saturated at an unacceptable level.
- Current Transformer and Second Circuit Insulation Resistance Tests
 - All insulation resistance testing results were satisfactory.

Corrective Action Plan

- Corrective Action Recommendations:
 - In order to address the under dimensioned CT concerns, the differential relay setting was increased in order to reduce the likelihood of undesirable operations for similar fault events.
- Fault studies confirmed that de-sensitizing the relays did not impact protection dependability.

Lessons Learned

- Avoid wired parallel connections of CTs.
- Install or retrofit CTs of appropriate accuracy class and ratio.
- Assess CT accuracy and performance during the design phase.
- Establish standard CT application categories.
- Specify standard CTs including accuracy class, use of full tap, etc.
- Confirm CT and scheme performance at the extreme fault scenarios to reduce CT saturations and misoperations.
- Check wiring conditions, insulation performance, and circuit grounding during commissioning.
- Develop standard relay setting criteria, especially for differential relays.



