

Effect of Transformer Connection and Construction on Single Phasing Detection

Gerald Johnson - Basler Electric Company

Randy Hamilton - Basler Electric Company

Sudhir Thakur - Exelon Corporation



Introduction

- On January 30, 2012 Exelon's Byron Unit 2 experienced an event, resulting in a unit trip & loss of off site power.
- Event: Insulator failure on 345kV offsite power source caused phase "C" S Bus "break away" from the power line disconnect switch.

Introduction

- As a result, both Unit 2 System Auxiliary Transformers (SATs) were single phased.
- Phase “C” of both SATs had a high Z ground
- Switchyard protective relaying is not designed to detect a single phasing event, did not operate
- SAT protection, including secondary Degraded Voltage Relay protection was not sensitive enough to detect the single phasing condition, did not operate

Byron Generating Station Unit 2 Switchyard



Background

Byron Auxiliary Power System

- Each Unit has two SATs
 - 142-1/142-2 for Unit 1
 - 242-1/242-2 for Unit 2
- Each SAT
 - Has 3-windings
 - Is Wye/wye-wye connected
 - Step down 345 kV/6.9 kV – 4.16 kV
 - Is a 3 legged core form transformer


Background

Byron Auxiliary Power System

- SAT 345kV primary winding is solidly grounded
- Secondary's are resistance grounded
 - 4.16 kV winding
 - supplies one division of Engineered Safety Features, ESF buses (safety bus) and one Non-ESF
 - 6.9 kV winding
 - supplies two Non-ESF buses

Byron Unit 2 Auxiliary Power System

One Line Diagram



Notes:


- 1) 4KV ESF buses are powered by SAT and EDG
- 2) Second off-site source to 4KV ESF buses is through opposite unit cross-tie breakers
- 3) Non-ESF buses have UAT and SAT feeds with Fast Bus Transfer scheme

Background

Byron Auxiliary Power System

- **SAT high side for a given unit connects to a common 345kV switchyard bus section**
- **Connection to SATs**
 - **from the 345kV bus**
 - **through a solid pipe “S-Bus”**
 - **through flexible connections**
 - **into the revenue metering “combo units”**
 - **to a common bus for both SATs**


Byron Auxiliary Power Transformer Connection



Byron Unit 2 Post Failure

Station

Switchyard



Byron Unit 2 Switchyard "C" Phase Failure



Root Cause

- **Manufacturing defect; porcelain was not fully fired in the kiln. Forensic Evaluation**
 - Failure caused by service propagation of a manufacturing material defect that covered approximately 40% of the fracture cross-section.
 - Defect was characterized as poorly vitrified porcelain containing a high density of porosity and micro-cracks.
 - No evidence the internal porcelain defect was open to external surface of the insulator until the final fracture
 - No evidence external cracking or a projectile impact preceded the failure

Bus Insulator Fracture



Root Cause

- The insulator failure
 - Ohio Brass under hung four stack insulator manufactured in 1977
 - Byron had experienced failures of these insulators in the past
 - The previous failures were on rotating switches
 - Failure mode believed to be related to the torque on the porcelain during switch operation
 - All switches in this application had been replaced

Byron Auxiliary Power System

- **On a loss of SATs, non-safety buses fast-transfer to Unit Aux TXs (UATs) and safety buses load onto the emergency diesels**
- **Second source of offsite power is opposite unit SAT through operator (manual) action**

The Event

- On January 30, 2012, 345kV switchyard “C” phase insulator fails leading to loss of “C” phase power to both Unit 2 SATs
- Resulting voltage imbalance cascades to the station buses through the SAT
- Reactor trips on RCP bus under voltage (2 out of 4 logic) fed from SAT .
- Motor driven and diesel driven Auxiliary Feedwater (AF) pumps receive signal to start on RCP bus under voltage
 - Diesel driven AF pump starts successfully.
 - Motor driven AF Pump does not accelerate (was powered from SAT)

The Event

- **Essential Service Water, Component Cooling, and Condensate Booster pumps trip on overcurrent.**
- **The degraded voltage relay scheme actuates and alarms following the 10 second time delay; however, the alarm clears in approximately 2 seconds**
- **Additional loads continue to trip on overcurrent**
- **Small loads trip due to TOL relays**
- **Approximately 30 seconds after the Reactor Trip, the Reverse Power Main Generator Trip occurs as expected**


The Event

- **Fast bus transfer occurs from UAT to SAT**
- **The remaining 2 RCPs trip following transfer**
- **Operators recognize the voltage imbalance 8 minutes into the event and manually open SAT feeds to all buses**
- **Emergency Diesel Generators (EDGs) automatically start and re-energize the safety buses**
- **An Unusual Event is declared**

The Event

- 4KV non safety related buses are subsequently re-energized from the 4kV safety buses to provide EDG power to select non-1E loads
- The switchyard insulator is repaired next day, off site power is restored.
- Unusual Event is terminated

Byron Unit 2 Auxiliary Power System One Line Diagram



Notes:

- 1) 4KV ESF buses are powered by SAT and EDG
- 2) Second off-site source to 4KV ESF buses is through opposite unit cross-tie breakers
- 3) Non-ESF buses have UAT and SAT feeds with Fast Bus Transfer scheme

Event

Design and Licensing Basis

- **Event revealed a design vulnerability not detected by the existing protective relay schemes**
 - **Switchyard protective relaying is not designed to detect this open phase event**
 - **Existing SAT protection was not sensitive enough to detect the open phase condition**
 - **Detection down to the level of this type of failure is beyond the requirements of GDC 17 or BTP PSB-1**
- **A Loss-of-Coolant-Accident (LOCA) coincident with this switchyard event is considered to be beyond the existing design and licensing basis of the plant**

Event Design Vulnerability

- **The degraded grid voltage relay scheme on the 4.16kV safety bus is not designed to actuate for voltage unbalance created by an open phase between offsite grid and SAT**
- **Degraded grid voltage relays on the 4.16kV safety bus provide isolation from the offsite grid and the automatic start and loading of the emergency onsite diesel gens**

Degraded Voltage Relay Scheme Description

- **The Degraded Voltage Relay (DVR) protection scheme consists of two under voltage relays on each 4kv ESF buses (AB, BC)**
- **Two separate time delays are provided:**
 - **A 10 second delay = sustained degraded voltage condition = alarm in Cont Room**
 - **A 5 minute delay to allow for restoration of voltage through operator action**
 - **After delay, 4kv ESF buses separate from offsite power, switch to respective EDG. If a Safety Injection actuation signal is received during 5 minute delay, the 4kv ESF buses will immediately be separated from the offsite power source**

Wye-G/Wye-G Transformer Bank 3-legged Core Form Analysis


- Note for this analysis:
 - (a) no flux passes through air
 - (b) $\Phi_A + \Phi_B = -\Phi_C$
 - (c) the flux in the A or B legs is defined by the A and B voltages

Wye-G/Wye-G Transformer Bank 3-legged Core Form Analysis

When primary phase C is disconnected:

- Phase A leg flux is proportional to $120 \angle 0^\circ$
- Phase B leg flux is proportional at $120 \angle -120^\circ$
- Phase C leg flux is initially unknown
- Ideally, sum of the fluxes must equal zero in a three legged core:
 - Flux A + Flux B + Flux C = 0 or:
 - Flux C = - (Flux A + Flux B) = - ($120 \angle 0^\circ + 120 \angle -120^\circ$) = - ($120 \angle -60^\circ$) = $120 \angle 120^\circ$,
replicating the missing voltage and angle


Three-Legged Core-Type Transformer Magnetic Paths




Wye-G/Wye-G Transformer Bank Analysis

- **Open phase on the 345kV primary A, B, or C phases results in unpredictable change of the low side voltage depending on load & high z ground**
- **Different flux patterns are the result of having closed or open zero sequence current paths depending on the ground connection of the primary (high voltage) winding**


Test Connection for Open Phase with Ground Simulation




Test TX, Normal 3-Phase Connection



Test TX, "C" Open



Test TX, "C" Phase Open with 20 ohm Ground on "C" Phase



Existing Protection Schemes

- The degraded voltage scheme is not sensitive enough to detect this condition.
 - For wye/wye-wye connected transformers with a three legged core, the inter-phase flux coupling keeps the secondary voltage on the open phase close to the normal value.
 - For the units without a buried delta, the zero sequence flux path is through the tank which acts as a high impedance delta.

New Protection Scheme

- **Installing a microprocessor based relay solution using current detection and also using symmetrical component currents supervising the trip output to provide security.**
 - **Monitors primary side (high voltage side) current.**
 - **Not dependent on the voltage**
 - **Proof of concept testing has been successfully completed**
 - **This scheme is being implemented at Byron using existing CTs.**


New Protection Scheme (Cont'd)

- **Exelon performed extensive EMTP studies to assure both dependability as well as security under different conditions**
 - **Normal system unbalance,**
 - **Downstream faults on the LV side**
 - **Coordination with upstream protective devices (line relaying)**
 - **Transients on the system**

EMTP Studies

- Exelon modeled more than 200 scenarios (see link Appendix A at end of paper).
- Analyzed scenarios included the following:
 - Unbalance in the grid: The unbalance can cause both negative and zero sequence voltages in the source voltage.
 - Variations in the grid voltage: Both maximum and minimum grid voltages were considered.
 - Faults on the transmission line: The relay must coordinate with back up line relaying.
 - Faults in the plant auxiliary system.
 - Transformer Energization.
 - Unequal loading of the two SATs.
 - Light and heavy loading on the auxiliary buses.
 - Motor starting and bus transfer scenarios.


Example using CTs from the High Side of the Transformer and a Microprocessor-Based Relay



Byron Unit 1 Event 02/28/2012

- On February 28, 2012 Byron Unit 1 experienced a similar failure when the A-phase under hung insulator separated
- A-phase connection still connected to disconnect switch
- Connection to revenue metering combo unit pulls out
- Source to SATs open to switchyard
- A-phase to switchyard grounded
- 30kA phase to ground fault
 - Fault cleared in 3 cycles
 - Ground fault, phase overcurrent and differential relays actuated.
 - Non-safety buses transferred to UAT
 - EDGs started, re-energized safety loads

Byron Unit 1 Post Failure



Conclusions

- The open phase or open phase grounded may be difficult to detect.
 - Transformer design may hold the voltage on the degraded phase high, independent of the actual current in the winding.
 - Transformer loading may render schemes insensitive to this fault condition.
 - Trip settings high enough to support maximum expected load compared to a much lower normal load.

Conclusions

- **Current only schemes will detect the condition but are subject to false tripping.**
 - Many transients have similar symptoms as the open phase or open phase grounded.
- **A Microprocessor based relay solution using current detection AND symmetrical component current supervision for the trip output, provide security and dependability.**

Questions?